Avocent[®] ACS 5000 Advanced Console Server Plug-in for the Avocent[®] DSView[™] Management Software Release Notes Version 3.3.7 September 22, 2016

This document outlines:

- 1. Update Instructions
- 2. Plug-in Software Version and Language Support Information
- 3. Fixed Issues
- 4. Known Issues

1. Instructions

IMPORTANT NOTES:

- The Avocent® ACS 5000 console server plug-in version 3.3.7 requires Avocent® DSView™ management software version 4.5.0.263 or later.
- The appliance firmware version is required to be version 3.3.0-18.
- Please refer to the ACS 5000 installation/administration/user guide for detailed instructions on updating the ACS 5000 console server to version 3.3.0-18. You can also refer to the DSView[™] 4.5 software installer/user guide for more information.

2. Plug-in Software Version and Language Support Information

The following languages are supported by the ACS 5000 console server plug-in version 3.3.7:

- English
- Japanese
- Simplified Chinese

Appliance/Product	Software Type	Version	Filename
ACS 5000 Console Server (ACS 5004, ACS 5008, ACS 5016, ACS 5032 and ACS 5048 console server models)	ACS 5000 Console Server Plug-in for DSView™ software	3.3.7	plugin_ACS5000_3.3.7_160601.jar.zip plugin_ACS5000_3.3.7_160601.jar.zip.md5

3. Fixed Issues

This plug-in requires the appliance to run on version 3.3.0-18 or later and resolves the issue of an Avocent® ACS 5000 console server failing to be enrolled in the Avocent® DSView™ software using Java 8.

4. Known Issues

The following issues are still present in this release:

- The Sequence Interval and Reboot Delay parameters (available for ServerTech power devices) are global parameters applied to both units in a chain. Although those parameters are shown in the first and second units of the chain, the configuration entered for the first unit is valid for the whole chain, while the configuration entered for the second unit is ignored.
- The ACS 5000 console server plug-in only accepts the Link_local IPV6 address for the Default Gateway when adding an ACS 5000 console server to DSView™ 4 software and assigning it a static IPV6 address. This happens when the ACS 5000 console server is still not configured with an IP address and it is being added to DSView™ 4 software. The Default Gateway address can be changed later on the Appliance Settings -Network page if necessary.
- If the ACS 5000 console server is configured to Dual Stack (IPV4 and IPV6), IPV4 SNMP Managers
 must be configured using the IPV4 mapped IPV6 format. The IPV4 mapped IPV6 format consists in
 using "::FFFF:<followed by the IPV4 address>". As an example, the IPV4 address 192.168.10.10
 would be mapped IPV6 as "::ffff:192.168.10.10".
- If an ACS 5000 console server is added to the DSView[™] 4 software using the IPV4 (or IPV6) address type, the DSView[™] software will use this address for all later communication attempts with that ACS 5000 console server. If the ACS 5000 console server address type is later changed and that previous IP address is no longer valid, the appliance must be removed from the DSView[™] software and added again. Otherwise the IP address type will not be changed.
- When the ACS 5000 console server firmware version is upgraded from a version not supporting IPV6 (1.0.2 or earlier) to a version that does support it (3.3.0-5 or later), the IPV6 configuration will still be unavailable through the DSView™ 4 software until its topology data base is synchronized. This synchronization occurs automatically through the periodic update topology operation or it can be forced by executing a "Resync" operation in the DSView™ software.
- Spaces and tilde ('~') characters cannot be used in Target names. If those characters are used, pushName operations for the ACS 5000 console server will not work.
- PushNames of PDU names are not supported.
- Unique SSH keys are generated in the ACS 5000 console server as soon as it boots for the first time (from factory default configuration). This operation happens only once, and it takes about five minutes to complete. Only after that is it possible to add the ACS 5000 console server to the DSView™ software.
- For ACS 5000 console server serial port direct access through the DSView[™] 4 software built-in serial viewer to work properly, the serial ports must be configured for SSH use.

- It is not recommended that the user change the configuration performed by the Avocent® ACS 5000 console server plug-in in the ACS 5000 console server by directly editing its configuration files. Even if the configuration steps described in the appliance documentation are correctly followed, the ACS 5000 console server plug-in may no longer recognize the saved configuration. In some cases, not even the ACS 5000 console server Web or CLI interfaces are recommended for configuration if the ACS 5000 console server is being managed by DSView™ 4 software.
- For target devices that are associated (merged) to one or more outlets, the Status Auto-refresh option
 in the user profile configuration page should be set to a value greater than the default 30 seconds (five
 minutes is recommended).
- Existing known issues with dial-up to the ACS 5000 console server:
 - If the user needs to launch a serial session while a dial-up connection is established between the DSView™ 4 server and that appliance (this usually means a connection from the user workstation to the appliance), it will be necessary to enable the DSView™ software proxy tool on the System DSView Server Proxy Server page.
 - The IP address used for dial-up configuration cannot be the same as the primary network IP address.
 - On the Dial-Up Settings page, the following radio buttons or checkboxes do not have their state saved since they are used only to define actions to be taken when the Save button is selected: Change password, Set PPP IP addresses, Choose addresses Automatically/Manually, Reset Sequence Now, OTP Passphrase, Random Passphrase and Change Passphrase.
 - o The DSView[™] 4 software drops the dial-up connection by PPP idle time-out (default is two minutes). The dial-up connection will not be dropped if the user keeps accessing the appliance or the serial ports via DSView[™] 4 software.
- Run the Add Power Manager wizard with ports that have a PDU attached. Otherwise, if the CTS, CD or DSR are not active on the selected port, the wizard will take more than 100 seconds before displaying an error message.
- Per segment alarm current threshold support for 2-segment Cyclades Intelligent Power Distribution Units (IPDUs) is not available for IPDUs with firmware version 1.8.0 or earlier.
- Detection of a 2-segment Cyclades IPDU is failing when there is one Avocent® Power Management Power Distribution Unit (PM PDU) with version 1.3.0 in the chain before the 2-segment Cyclades IPDU. This problem affects the Power Device Add operation through DSView™ 4 software, because the chain will not be detected.
- If an ACS 5000 console server with ServerTech Smart CDU is added to more than one DSView[™] 4 software appliance and the Resync is run instead of the Add Power Device wizard, it is possible that the Smart CDU appears with Type "69" instead of "ServerTech Power Device" in the Unit Views of the DSView[™] 4 software. In this case, run the Remove Power Devices wizard in the DSView[™] 4 software that shows Type "69" and run the Add Power Devices wizard to fix the Type.

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, Cyclades and DSView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2016 Avocent Corporation. All rights reserved.