

Vertiv™ Avocent® ACS8xxx Advanced Console System Plug-in for the DSView™ Management Software

Release Notes

VERSION 2.16.0.9, JULY 15, 2021

Release Notes Section Outline

1. Update Instructions
2. Appliance Firmware Version Information
3. Features and Enhancements
4. TCP Port Information for Communication with the Avocent® ACS Console System

1. Update Instructions

IMPORTANT NOTE: The Vertiv™ Avocent® ACS8xxx advanced console system plug-in version 2.16.0.9 requires Vertiv™ Avocent® DSView™ management software version 4.5 SP12 or higher. It is also recommended to upgrade the Avocent® ACS8xxx advanced console system firmware to version 2.16.2.

2. Appliance Firmware Version Information

PRODUCT	SOFTWARE TYPE	VERSION	FILENAME
Vertiv™ Avocent® ACS8xxx advanced console system	Vertiv™ Avocent® ACS8xxx advanced console system plug-in for Vertiv™	2.16.0.9	plugin_ACS8000_2.16.0.9_210624.jar.zip
	Avocent® DSView™ software		plugin_ACS8000_2.16.0.9_210624.jar.zip.sha2.txt

3. Features and Enhancements

The Vertiv™ Avocent® ACS8xxx advanced console system version 2.16.0.9 plug-in allows you to manage the Vertiv™ Avocent® ACS8xxx advanced console system appliance family from the Vertiv™ Avocent® Avocent® DSView™ software. Please refer to the user guide accompanying the Vertiv™ Avocent® ACS8xxx advanced console system for additional details about supported system features.

- Added a fix for Vertiv™ Avocent® DSView™ software serial sessions failing if there is a space in the target name.
- Added a fix for the display of Vertiv™ Avocent® ACS advanced console system pages in the Vertiv™ Avocent® DSView™ software.
- Added a fix for the Vertiv™ Avocent® DSView™ software user interface missing parameters.
- Added a fix for Vertiv™ Avocent® DSView software SSH passthrough to the Vertiv™ Avocent® ACS advanced console system with FIPS mode enabled.
- Added a fix for the Vertiv™ Avocent® DSView™ software Upgrade Firmware task failing when multiple Vertiv™ Avocent® ACS advanced console system units are upgraded in parallel.
- Added a fix for the Digital In sensor page; it was not showing the correct state for the Alarm field between the Vertiv™ Avocent® DSView™ software and the Vertiv™ Avocent® ACS advanced console system.
- Added a fix for a Power Distribution Unit (PDU) status message display issue.

4. TCP Port Information for Communication with the Avocent® ACS Console System

The following appliance ports can accept connections from the Vertiv™ Avocent® DSView™ software:

- TCP port 3502 (https)
- TCP port 3871 (adsap2)
- UDP port 3211 (aidp)
- TCP port 22 (sshd)

Additionally, these are the ports in the Vertiv™ Avocent® DSView™ software that can accept connections from the appliance:

- TCP port 4122 (default, it can be changed – SSH Server)
- TCP port 4514 (default, it can be changed – Data Logging or Syslog Server)