
Avocent® AutoView™ 2108/2216 Switch Firmware

Release Notes

Version 1.18.4

December 18, 2015

This document outlines:

1. Appliance Support Information
2. Fixes
3. Client / Browser Information

1. Appliance Support Information

The following appliances are supported with this release.

AutoView™ Switch	Firmware
AV2108	FL0674-AVO-1.18.4.0.3956.fl
AV2216	

NOTE: For CentOS targets, use a single or dual mouse cursor with AMS disabled.

2. Fixes

- Java KVM session freezes after exiting Map Smart Card window and attempting to re-open
- Updated JAVA and Active X viewer certificates
- L3 487234_510035024: Green tint on on local port with HP Gen 9 server as target

3. Client / Browser Information

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 60
Internet Explorer	11
Firefox	41
Chrome	46

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and AutoView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.