
Avocent® AutoView™ 2108/2216 Switch Firmware Release Notes Version 1.26.0 May 12, 2017

This document outlines:

1. Appliance Support Information
2. Enhancements
3. Fixes
4. Notes
5. Client / Browser Information

1. Appliance Support Information

The following appliances are supported with this release.

AutoView™ Switch	Firmware
AV2108	FL0674-AVO-1.26.0.0.4244.fl
AV2216	

2. Enhancements

- Rebranding within the On-board Web Interface (OBWI) and the local port user interfaces
- DES and 3DES ciphers removed from user interfaces (keyboard, mouse, video and virtual media)
- IDEA, SEED and CAMELLIA ciphers removed from Port 443 (OBWI)
- TLS 1.1 protocol disabled on Port 443 (OBWI)
- Added support for all Dell SIP modules
- Added support for the following Dell ACI cascaded appliances (SKU numbers):
 - DMPU108E / 2016 / 4032
 - DAV2108 / 2216
 - 1082DS / 2162DS / 4322DS
 - 1081AD / 2161AD
- Improved product security

3. Fixes

L3 #487234-674084682: VT100 serial RIP defaulting to the wrong screen mode/width.

4. Notes

- Firmware version 1.20 or higher is required to support JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5), and Avocent® AutoView™ switch plug-in, version 1.20.1
 - Compatible with JAVA 7-based DSView™ software from version 4.5.0.108 to 4.5.0.247.
-
-

5. Client / Browser Information

NOTE: Microsoft® Internet Explorer® versions 8 and 9 are no longer supported as client browsers. Also, Firefox 52 ESR 64-bit (and above) is not supported due to Firefox limits of NPAPI support.

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 131
Internet Explorer	11
Firefox	53.0
Firefox ESR	52.0 - 32 bit ONLY
Chrome	58