
Avocent® AutoView™ 3008/3016 Switch
Release Notes
Version 1.1.1.10
December 18, 2015

This document outlines:

1. Appliance Firmware Version Information
2. Enhancements
3. Fixes
4. Flash Update Failure Recovery

=====

1. Appliance Firmware Version Information

=====

The following appliances are supported with this update:

Switch	Firmware
AutoView™ 3008/3016 Switches	avocent_3008_3016_1.1.1.10.fl

=====

2. Enhancements

=====

- OpenSSL updated for “GHOST” vulnerability
- Support for JAVA 8 Update 60

=====

3. Fixes

=====

- Updated JAVA and Active X viewer certificates

=====

4. Flash Update Failure Recovery

=====

If the green power LED on the back panel of the AutoView™ switch blinks every two seconds, the switch is in recovery mode.

To recover from a failed Flash upgrade:

1. Set up the TFTP server with server IP address 10.0.0.20.
2. Rename the Flash update file to the appropriate filename and place it into the appropriate directory on the TFTP server: AutoView 3008, 3016 - CMN-1082.fl
3. If the AutoView™ switch is not on, turn it on now.

4. The recovery process will start automatically.

NOTE: If you do not have a TFTP server, there are several shareware and freeware programs on the Internet that you can download and install.

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and AutoView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.