
Avocent® AutoView™ 3008/3016 Switch

Release Notes

Version 1.1.1.12

January 20, 2017

This document outlines:

1. Appliance Firmware Version Information
2. Enhancements
3. Fixes
4. Client/Browser Information
5. Flash Update Failure Recovery

1. Appliance Firmware Version Information

The following appliances are supported with this update:

Switch	Firmware
AutoView™ 3008/3016 Switches	avocent_3008_3016_1.1.1.12.fl

2. Enhancements

- Firefox browser Version 48 support
- RC4 and DES and 3DES ciphers removed from Port 443 [On-Board Web Interface (OBWI)]
- Improved product security

3. Fixes

L3 #487234-612094764: TLS 1.0 protocol enabled on Port 443 (OBWI)

4. Client / Browser Information

NOTE: Microsoft® Internet Explorer® versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 101

Software	Version
Internet Explorer	11
Firefox	49.02
Firefox ESR	45.5.1

5. Flash Update Failure Recovery

If the green power LED on the back panel of the Avocent® AutoView™ switch blinks every two seconds, the switch is in recovery mode.

To recover from a failed Flash upgrade:

1. Set up the TFTP server with server IP address 10.0.0.20.
2. Rename the Flash update file to the appropriate filename and place it into the appropriate directory on the TFTP server: AutoView 3008, 3016 - CMN-1082.fl
3. If the AutoView™ switch is not on, turn it on now.
4. The recovery process will start automatically.

NOTE: If you do not have a TFTP server, there are several shareware and freeware programs on the Internet that you can download and install.