
Avocent® AutoView™ 3x00/3050 Switch
Release Notes
Version 1.7.0.4
December 18, 2015

This document outlines:

1. Update Instructions
2. Enhancements
3. Fixes
4. Flash Update Failure Recovery

=====

1. Update Instructions

=====

Please refer to your user manual for detailed instructions to update the switch.

=====

2. Enhancements

=====

- OpenSSL updated for “GHOST” vulnerability
 - Support for JAVA 8 Update 60
- =====

3. Fixes

=====

- Updated JAVA and Active X viewer certificates
 - 487234-471028834: SSL certificate uses 2048 bits key length
 - L3 487234-498963865: LDAP stopped working at v1.7.0.0
- =====

4. Flash Update Failure Recovery

=====

If the green power LED on the front and back panel of the switch blinks continuously, the switch is in recovery mode.

To recover from a failed Flash upgrade:

1. Set up the TFTP server with server IP address 192.168.1.254.
2. Rename the Flash update file to the appropriate filename from the following list and place it into the appropriate directory on the TFTP server.

Switch	Filename
AutoView 3050 Switch	AV3050.fl
AutoView 3100/3200 Switches	AV3x00.fl

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and AutoView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.