
Avocent® AutoView™ Switch for Dell

Firmware Release Notes

Version 1.20.0

April 29, 2016

This document outlines:

1. Appliance Support Information
2. Enhancements
3. Fixes
4. Client/Browser Information

1. Appliance Support Information

The following appliances are supported with this release.

Switch	Firmware
DAV2108	FL0652-AVODELL-1.20.0.0.4039.fl
DAV2216	

2. Enhancements

- Appliance web certificate supports SHA-256 cryptography
- RC4 cipher removed from Port 443 [On-Board Web Interface (OBWI)]
- Required to support JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5), and Avocent® AutoView™ switch plug-in, version 1.20.1
- Compatible with JAVA 7-based DSView™ software from version 4.5.0.108 to 4.5.0.247
- Improved product security

3. Fixes

- L3 #487234-534590816: Local Port B On-Screen Display (OSD) flag does not accept configuration changes
- OBWI appliance firmware HTTP and FTP download methods not working
- Toshiba® C45 BIOS screens shifted

4. Client/Browser Information

NOTE: Microsoft® Internet Explorer® versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 77
Internet Explorer	11
Firefox	44
Firefox ESR	24.1
Chrome	46

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo, AutoView and DSView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2016 Avocent Corporation. All rights reserved.