

VERTIV™

Avocent® AutoView™ Switch for Dell Firmware Release Notes

VERSION 1.30.1, MAY 11, 2018

Release Notes Section Outline

- 1 Appliance Support Information
- 2 Enhancements
- 3 Fixes
- 4 Notes
- 5 Client/Browser Information

1 Appliance Support Information

The following appliances are supported with this release.

SWITCH	FIRMWARE
DAV2108	FL0652-AVODELL-1.30.1.0.4396.fl
DAV2216	FL0652-AVODELL-1.30.1.0.4396.fl

NOTE: Firmware updates to version 1.30.1 and higher are NOT reversible to firmware versions earlier than 1.30.1.

2 Enhancements

This release improves product security.

3 Fixes

- MPUIQ-VMCHS module server name resets to the default name after reboot (L3 #487234-601393331, #487234-524868294)
- In Firefox and IE, *Java Not Installed* message fixed
- Single mouse cursor was not supported on Mac clients (L3 #487234-767855963)

4 Notes

Firmware version 1.30.1 requires the Avocent® AutoView™ switch for Dell plug-in, version 1.30.0, if the appliance is to be enrolled in Avocent® DSView™ management software.

5 Client/Browser Information

NOTE: Microsoft® Internet Explorer® versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	9.0.4
Internet Explorer	11
Firefox	59.0.2
Firefox ESR	52.0 - 32 bit ONLY
Chrome	65.0.3325.181

NOTE: Firefox 52 ESR 64-bit (and higher) is not supported due to the Firefox limits of NPAPI support.