

This is a general maintenance release to the DSR1030, 2030, 4030 and 8030 switch appliance product line exclusively compatible with DSView® 3 software.

This document outlines:

1. Appliance Version Information
2. DSR Switch Appliance Localization File Information
3. Enhancements/Fixes/Known Issues

---

---

Appliance Version Information

---

---

The following switch appliances are supported with this release:

<u>Switch Appliance</u>	<u>Application Image</u>
DSR1030/2030/4030/8030	3.1.0.11

---

---

DSR Switch Appliance Localization File Information

---

---

The following localization of the OSCAR® OSD for the DSR switch appliances is supported with this update:

<u>Language</u>	<u>File Name</u>
English	English_FL0439.fl
French	French_FL0443.fl
German	German_FL0441.fl
Spanish	Spanish_FL0442.fl
Italian	Italian_FL0440.fl

---

---

Enhancements

---

---

This release contains the following enhancements:

1. Allow OSCAR interface password to contain all printable characters.
2. Allow selection of OSCAR OSD invocation key sequence:
  - Ctrl-Ctrl
  - Alt-Alt
  - Shift-Shift
  - Print Screen

---

---

## Fixes

---

---

This release contains the following fixes:

1. Local Port Session Terminated trap not being generated.
2. Virtual Media Session Terminated trap not being generated
3. Front panel USB port not recognizing Teac #CD-210PU USB CDROM drive

---

---

## Known Issues

---

---

This release contains the following known issues:

1. Not applicable