
**Avocent® SwitchView™ 1000 Switch
Release Notes
Version A7
March 21, 2017**

This document outlines:

1. Appliance Firmware Version Information
2. Fixes

=====

1. Appliance Firmware Version Information

=====

The following appliances are supported with this update.

Switch	Firmware
Avocent® SwitchView™ 1000 Switches	u088-14-06-25.uni

NOTE: For additional product information, including upgrading instructions, see the Avocent® SwitchView 1000 Switch Installer/User Guide, also available at www.avocent.com/manuals. If you need additional support, contact Technical Support by visiting www.emersonnetworkpower.com/support or dialing 1-888-793-8763.

=====

2. Fixes

=====

- Resolved Error 55 message
- Added driver to convert apple 220 KB consumer key to standard HID format

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and SwitchView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2017 Avocent Corporation. All rights reserved.