

AdminWorks™
Revision 1.2.12.96
Release Notes
November 30, 2005

This document outlines:

1. Important Installation Notes
2. Enhancements
3. Fixes
4. Known Issues

Important Installation Notes

This release adds "Console Only" setup option for installation, so the IDU users will be able to install AdminWorks Management Software 1.2 without uninstalling their previously installed IDU. We have also improved the stability of program, based on latest build of the OEM project for Acer.

Enhancements

This release of software contains the following enhancements:
This release is for adding the "Console Only" setup option for installation, so the IDU users will be able to install AdminWorks Management Software 1.2 without uninstalling their previously installed IDU.

Fixes

This release of software contains the following fixes:

1. Add the "Console Only" option for installation.
 2. The Console will show "Accessing Sensor Data..." in the Information Frame, instead of "Sensor Not Detected", before the Console has retrieved the sensor data successfully from the Agent. In the previous version, "Sensor Not Detected" was always showing before the sensor data retrieved from the agent successfully, no matter whether the sensor could be detected or not.
 3. Improve the performance of Health monitoring.
 4. When the trial version expires, the Report Generator cannot be activated even if a valid Activation Key has been entered.
 5. 64-bit OS support.
 6. The string of HD size in Health would be truncated when the size was larger than 100GB.
 7. On some uncertain condition, the Console program would show "Access violation error".
 8. The memory leak issue which caused the Console process to consume more and more memory space during discovery.
 9. Change the mechanism for resource loading to improve the efficiency of program launch.
 10. The exported data from Report Generator does not include all of the installed HDDs when there are multiple HDDs are installed on the system.
-
-

Known Issues

This release of software contains the following known issues: