

Cyclades® PM Appliances
Release Notes
Version 1.9.4
April 07, 2011

This document outlines:

1. Update Instructions
2. Appliance Firmware Version
3. Enhancements
4. Fixes
5. Known Issues

Update Instructions

Please refer to your Installation, Administrator and User manual for detailed instructions to update the Intelligent Power Distribution Unit Cyclades® PM appliance to version 1.9.4.

This firmware version is specific to be used in Cyclades® PM connected to serial port of one of the following Cyclades advanced console server families: ACS, ACS 5000 and ACS 6000.

When PDU is connect to ACS or ACS 5000, the upgrade via management software DSView® 3 requires Cyclades® ACS Plug-in v 3.3.4 or Cyclades® ACS 5000 Plug-in v 3.3.4.

NOTE: This firmware should NOT be upgraded in Cyclades® PM42.

Appliance Firmware Version

Appliance/Product	Firmware Type	Version	Filename	Part Number
Cyclades® PM	Opcode	V_1.9.4	FL0542-004.bin FL0542-004.bin.md5 FL0542-004.pkg	FL0542-004

Enhancements

No new enhancements to Cyclades® PM for this release v1.9.4.

Fixes

Cyclades® PM 1.9.4 contains the fix for losing PDUs in a chain connected to serial port of Cyclades® ACS or Cyclades® ACS 5000.

Known Issues

Cyclades® PM 1.9.4 contains the following known issues:

1. *dbsync* command since version 1.9.2 is not compatible with 1.9.0, so issuing this command in a chain with both versions may not synchronize correctly the user databases.
2. PM doesn't invalidate some commands when there are more arguments than specified in the syntax.
3. The boot message still mentions *AlterPath*[™]. This is necessary in order to assure daisy-chaining compatibility with older versions.

Cyclades® is registered by Avocent Corporation in the United States and other countries.
DSView® is registered by Avocent Corporation in the United States and other countries.