
Avocent® ACS 6000 Advanced Console Server

Release Notes

Version 3.1.0.9

July 20, 2015

This document outlines:

1. Update Instructions
2. Appliance Firmware Version Information
3. Features/Enhancements
4. Bug Fixes

1. Update Instructions

NOTE: Please refer to the ACS 6000 Installation/Administration/User Guide for detailed instructions on updating the ACS 6000 console server to version 3.1.0

IMPORTANT NOTE: This version should be upgraded from version 2.5.0-11 or newer. Appliances with earlier versions should be upgraded to version 2.5.0-11 or newer before the upgrade to version 3.1.0.9.

In order to have all features listed in this release available through DSView™ management software, DSView™ software version 4.5.0.123 or later and ACS 6000 console server plug-in version 3.1.0.4 are required.

After the ACS 6000 console server firmware has been upgraded to version 3.1.0, it is mandatory that the web browser cache of any system which intends to be connected to the ACS 6000 console server web interface is cleared. To do this, press **Ctrl-F5** from the browser.

ACS 6000 console server firmware version 3.1.0 provides an internal mechanism which preserves the existing configuration when upgrading from firmware version 3.0.0. However, it is strongly recommended that you back up the system configuration before the firmware version upgrade.

2. Appliance Firmware Version Information

Appliance/Product	Firmware Type	Version	Filename
Avocent® ACS 6000 Console Server	Opcode	V_3.1.0.9	avolmage_avctacs-3.1.0-9.bin avolmage_avctacs-3.1.0-9.bin.md5

3. Features/Enhancements

NOTE: Please refer to the ACS 6000 Installation/Administration/User Guide and/or Command Reference Guide for details about features supported by the ACS 6000 console server version 3.1.0.

Client Browser Support Information:

- Microsoft® Internet Explorer® 11
- Mozilla® Firefox® version 36.0.1 in Windows 7.

-
- Google Chrome™ browser version 41.0 in Windows 7.
 - Enhancements in Security Profile:
 - Allows users to select TLS version 1.1 and/or 1.2, with or without TLS 1.0.

NOTE: TLS 1.0 is required for DSView™ software integration.

4. Bug Fixes

Bug fixes include in version 3.1.0.9:

- Password less ssh authentication using RSA key pair. (L3-487234-414562739)

Emerson and Emerson Network Power are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and DSView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.