

VERTIV™

Avocent® AutoView™ 2108/2216 Switch Firmware Release Notes

VERSION 2.2.0, OCTOBER 28, 2019

Release Notes Section Outline

- 1 Appliance Support Information
- 2 Enhancements
- 3 Notes
- 4 Client/Browser Information

1 Appliance Support Information

The following appliances are supported with this release.

AUTOVIEW™ SWITCH	FIRMWARE
AV2108	FL0674- AVO-2.2.0.4508.fl
AV2216	FL0674-AVO-2.2.0.4508.fl

NOTE: Firmware updates to version 1.30.1 and higher are NOT reversible to firmware versions earlier than 1.30.1.

2 Enhancements

This release adds the following enhancements:

- Compliance with the California IoT Senate Bill No. 327:
 - “Admin” is the default user and there is no default password. Following initial power up, or after a Factory Reset, the first time the Admin user logs into the On-Board Web Interface (OBWI), the user is required to create and confirm a new password.
 - Following a firmware upgrade, no password change is required for the Admin default user unless the local user database is still in the factory default state. If no local user accounts have ever been added or edited prior to the firmware upgrade, then the user is required to create a password for the Admin default user.
- Added support for local port monitors that only accept 60 Hz video modes:
 - OBWI menu option located under *Sessions- KVM- Hardware Presented*
 - Local port OSCAR™ on-screen graphical user interface menu located under *Setup-Video*
 - Default: Enabled
- Improved product security

3 Notes

Firmware version 2.2.0 requires the Avocent® AutoView™ switch plug-in, version 1.30.1, if the appliance is to be enrolled in Avocent® DSView™ management software.

4 Client/Browser Information

NOTE: Microsoft Internet Explorer versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	1.8.0.201
Internet Explorer	11
Firefox	68.0.1 (64-bit)
Firefox ESR	60.3.0 ESR (64-bit)
Chrome	Version 75.0.3770.142 (Official Build) (64-bit)