

Vertiv™ Avocent® AutoView™ 2108/2216 Switch

Firmware Release Notes

VERSION 2.8.3, APRIL 2023

Release Notes Section Outline

1. Appliance Support Information
2. Enhancements
3. Notes
4. Client/Browser Information
5. Java Viewer Session Expired Certificate Information

1. Appliance Support Information

The following appliances are supported with this release.

VERTIV™ AVOCENT® AUTOVIEW™ SWITCH	FIRMWARE
AV2108	FL0674-AVO-2.8.3.0.4693.fl
AV2216	FL0674-AVO-2.8.3.0.4693.fl

NOTE: Firmware updates to version 1.30.1 and higher are NOT reversible to firmware versions earlier than 1.30.1.

2. Enhancements

This release adds the following enhancements:

- Added an option for the On-Board Web Interface (OBWI) to enable/disable TCP port 3871 (the ADSAP2 port).
- Added updates so that a reboot is no longer required after uploading a third-party web certificate.
- Updated localization for the OBWI and the HTML5 viewer.
- Improved product security.

3. Notes

Firmware version 2.8.3 requires the Vertiv™ Avocent® AutoView™ switch plug-in, version 1.31.0, if the appliance is to be enrolled in Vertiv™ Avocent® DSVIEW™ management software.

4. Client/Browser Information

NOTE: Microsoft Internet Explorer versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	1.8.0.291
Internet Explorer	11
Firefox	107.0 (64-bit)
Chrome	108.0.5359.125 (64-bit)
Edge	108.0.1462.54 (64-bit)

5. Java Viewer Session Expired Certificate Information

Java KVM viewer session certificates existing in older firmware versions expired on September 26, 2021. After that date, Java prevents KVM sessions from launching unless you update to the newest firmware or edit the Java Console Security settings on each client computer by adding the appliance IP address in the Exception Site List.