

AutoView™ 3x00/3050 Switch Appliances
Firmware Release Notes
Version 1.6.0.8
September 21, 2012

1. Update Instructions
2. Enhancements
3. Fixes
4. Known Issues
5. Flash Update Failure Recovery

=====
Update Instructions
=====

Please refer to your user manual for detailed instructions to update the switch.

=====
Enhancements
=====

None

=====
Fixes
=====

This release contains the following fixes:

1. L3 65681874 – Video freezes if user chooses AES only for video encryption

=====
Known Issues
=====

This release contains no known issues.

=====

FLASH Update Failure Recovery

=====

If the green power LED on the front and back panel of the appliance blinks continuously, the switch is in recovery mode. Use the following steps to recover from a failed FLASH upgrade:

1. Set up the TFTP server with server IP address 192.168.1.254.
2. Rename the Flash update file to the appropriate filename from the following list and place it into the appropriate directory on the TFTP server.

Switch	Filename
AutoView™ 3050	AV3050.fl
AutoView™ 3100, AutoView™ 3200	AV3x00.fl