

# VERTIV™

## Avocent® AutoView™ 3108/3216 Switch

### Firmware Release Notes

**VERSION 2.0.0, JUNE 14, 2019**

#### Release Notes Section Outline

- 1 Appliance Support Information
- 2 Enhancements
- 3 Fixes
- 4 Notes
- 5 Client/Browser Information

#### 1 Appliance Support Information

The following appliances are supported with this release.

AUTOVIEW™ SWITCH	FIRMWARE
AV3108	FL0683-AVO-2.0.0.0.4476.fl
AV3216	FL0683-AVO-2.0.0.0.4476.fl

**NOTE:** Firmware updates to version 1.30.1 and higher are NOT reversible to firmware versions earlier than 1.30.1.

#### 2 Enhancements

This release adds the following enhancements:

- HTML5 viewer support:
  - TCP Port Number 4206 must be open to use this feature.
  - Chrome is the recommended browser when using the HTML5 viewer.
  - A remote HTML5 KVM session is launched by clicking the target name in the On-board Web Interface (OBWI), then clicking *KVM Session HTML 5*.
- Absolute Mouse Synchronization support
- Improved product security

#### 3 Fixes

- Fixed issue with smartcard readers not mapping on Windows 10 targets (L3 #487234-826626157)
- Fixed issue with remote KVM sessions not being established with Java Version 8 Update 201

#### 4 Notes

Firmware version 2.0.0 requires the Avocent® AutoView™ switch plug-in, version 1.30.1, if the appliance is to be enrolled in Avocent® DSView™ management software.

## 5 Client/Browser Information

**NOTE:** Microsoft Internet Explorer versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	1.8.0.201
Internet Explorer	11
Firefox	66.0.5 (64-bit)
Firefox ESR	60.3.0 ESR (64-bit)
Chrome	Version 74.0.3729.169 (Official Build) (64-bit)