

Vertiv[™] Avocent[®] MergePoint Unity[™] KVM over IP and Serial Console Switch

Firmware Release Notes

VERSION 2.12.4, SEPTEMBER 2023

Release Notes Section Outline

- 1. Update Instructions
- 2. Appliance Support Information
- 3. Enhancements
- 4. Notes
- 5. Known Issues
- 6. Client/Browser Information
- 7. Flash Update Failure Recovery
- 8. Java Viewer Session Expired Certificate Information

1. Update Instructions

For detailed instructions on updating your switch, please refer to your user documentation.

WARNING: After upgrading to version 2.12.4, the Vertiv[™] Avocent[®] MergePoint Unity[™] switch cannot be downgraded to a firmware version earlier than 2.12.4. For more information, contact Technical Support.

- Attaching the MPUIQ-VMC or DSRIQ-VMC module to a Windows target may require the USB CCID driver to be installed. If you are prompted by the Windows New Hardware Wizard, select the *Next* button.
- For Vertiv[™] Avocent[®] Power Management 2003, 2006, 2024, 3003, 3006 and 3024 Power Distribution Units (PM PDUs), version 1.10 firmware or higher is required to manage the PDU from the Vertiv[™] Avocent[®] MergePoint Unity[™] switch.

2. Appliance Support Information

The following appliances are supported with this release.

VERTIV™ AVOCENT® MERGEPOINT UNITY™ SWITCH	FIRMWARE
MPU104E	FL0620-AVO-2.12.4.26064.fl
MPU108E	FL0620-AVO-2.12.4.26064.fl
MPU108EDAC	FL0620-AVO-2.12.4.26064.fl
MPU1016	FL0620-AVO-2.12.4.26064.fl
MPU1016DAC	FL0620-AVO-2.12.4.26064.fl
MPU2016	FL0620-AVO-2.12.4.26064.fl



VERTIV™ AVOCENT® MERGEPOINT UNITY™ SWITCH	FIRMWARE
MPU2016DAC	FL0620-AVO-2.12.4.26064.fl
MPU2032	FL0620-AVO-2.12.4.26064.fl
MPU2032DAC	FL0620-AVO-2.12.4.26064.fl
MPU4032	FL0620-AVO-2.12.4.26064.fl
MPU4032DAC	FL0620-AVO-2.12.4.26064.fl
MPU8032	FL0620-AVO-2.12.4.26064.fl
MPU8032DAC	FL0620-AVO-2.12.4.26064.fl

NOTE: For CentOS targets, use a single or dual mouse cursor with AMS disabled.

3. Enhancements

This release adds the following enhancements:

• Improved product security.

4. Notes

If the appliance is going to be enrolled in the Avocent[®] DSView[™] management software, firmware version 2.12.4 requires Avocent[®] MergePoint Unity[™] switch plug-in version 2.10.0.

5. Known Issues

In order to share HTML5 sessions, sharing with stealth must be enabled.

6. Client/Browser Information

NOTE: Microsoft Internet Explorer versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	1.8.0.291
Internet Explorer	11
Firefox	107.0 (64 Bit)
Chrome	108.0.5359.125 (64 Bit)
Edge	108.0.1462.54 (64 Bit)



7. Flash Update Failure Recovery

If the switch doesn't boot into the new firmware after a Flash procedure, it is possible to revert to the previous firmware version.

WARNING: After upgrading to version 1.18.0.x, the Avocent[®] MergePoint Unity[™] switch cannot be downgraded to a firmware version earlier than 1.18.0.x. For more information, contact Technical Support.

To revert to the previous firmware version:

- 1. Connect a serial cable to the Setup port on the rear panel of the Avocent® MergePoint Unity™ switch.
- 2. Run a terminal program on the PC connected to the Setup port. The serial port settings should be: 9600 baud, 8 data bits, 1 stop bit, no parity and no flow control.
- 3. Turn on the Avocent[®] MergePoint Unity[™] switch.
- 4. Press any key when the Hit any key to stop autoboot prompt appears in the terminal program.
- 5. Once a menu is displayed in the terminal program, press 1 to select Boot Alternate, and then press Enter.
- 6. The Avocent[®] MergePoint Unity[™] switch will then reboot to the previous version automatically.

8. Java Viewer Session Expired Certificate Information

Java KVM viewer session certificates existing in older firmware versions expired on September 26, 2021. After that date, Java prevented KVM sessions from launching unless you update to the newest firmware or edit the Java Console Security settings on each client computer by adding the appliance IP address in the Exception Site List.

NOTE: Currently installed ActiveX viewers are not affected and are able to continue using the expired certificate.

© 2023 Vertiv Group Corp. All rights reserved. Vertiv[™] and the Vertiv logo are trademarks or registered trademarks of Vertiv Group Corp. All other names and logos referred to are trade names, trademarks or registered trademarks of their respective owners. While every precaution has been taken to ensure accuracy and completeness here, Vertiv Group Corp. assumes no responsibility, and disclaims all liability, for damages resulting from use of this information or for any errors or omissions.