Avocent® AutoView™ 3108/3216 Switch Firmware Release Notes Version 1.24.0 January 20, 2017

This document outlines:

1. Appliance Support Information
2. Enhancements
3. Fixes
4. Notes
5. Client / Browser Information

==

1. Appliance Support Information

==

The following appliances are supported with this release.

AutoView™ Switch	Firmware
AV3108	FL0683-BC-AVO-1.24.0.0.4170.fl
AV3216	

==

2. Enhancements

==

- Firefox browser Version 48 support
- DES and 3DES ciphers removed from Port 443 [On-Board Web Interface (OBWI)]
- Optional Target Port column in OBWI
- Improved product security

==

3. Fixes

==

- L3 #487234-405108972: KVM viewer does not pass '> <' key (German keyboard)
- L3 #487234-612094764: TLS 1.0 protocol enabled on Port 443 (OBWI)
- Remote OBWI does not start KVM session in PS2 cascade appliance configuration

==

4. Notes

==

- OBWI: The encryption level for keyboard/mouse must be set to AES. The encryption level for video and virtual media must be set to AES or None. The next firmware release will remove DES and 3DES from the encryption menu options as those ciphers are no longer supported.

- Firmware version 1.22.1 or higher is required to support the JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5) or higher, and Avocent® AutoView™ switch plug-in, version 1.22.0.

- Compatible with JAVA 7-based DSView™ software from version 4.5.0.108 to 4.5.0.247.

==

5. Client / Browser Information

==

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 101
Internet Explorer	11
Firefox	49.02
Firefox ESR	45.5.1
Chrome	55.0.2883.75