Avocent® MergePoint Unity™ KVM Over IP and Serial Console Switch for Dell Release Notes
Version 1.22.3
May 9, 2014

This document outlines:

1. Update Instructions

2. Appliance Firmware Version Information

3. Fixes

4. Flash Update Failure Recovery

===

1.   Update Instructions

===

Please refer to your user manual for detailed instructions on updating your MergePoint Unity™ switch for Dell.

===

2.   Appliance Firmware Version Information

===

The following appliances are supported with this update:

Switch	File Version
DMPU108E	FL0651-AVO-1.22.3.23249.fl
DMPU2016	FL0651-AVO-1.22.3.23249.fl
DMPU4032	FL0651-AVO-1.22.3.23249.fl

===

3.   Fixes

===

- Java 7 update 51 blocking KVM and serial sessions
- Double keystroke with Linux client

===

4.   Flash Update Failure Recovery

===

If the switch does not boot into the new firmware version after a Flash procedure, it is possible to revert to the previous firmware version.

To revert to the previous version of firmware:

1. Connect a serial cable to the Setup port on the rear panel of the switch.

2. Run a terminal program on the PC connected to the Setup port. The serial port settings should be: 9600 baud, 8 data bits, 1 stop bit, no parity, and no flow control.

3. Turn on the switch.

4. In the terminal program, press any key when the *Hit any key to stop autoboot* prompt appears.

5. A menu displays on the terminal program. Press **1**, then **Enter** to select Boot Alternate.

6. The switch will reboots automatically to the previous firmware version.