SwitchView™ DVI Switches
Firmware Revision 8.12
Release Notes
May 15, 2009

This document outlines:
1. Update Instructions
2. Appliance Firmware Version and Language Support Information
3. Enhancements
4. Fixes
5. Known Issues
6. Model Applicability

===
Update Instructions
===
Please refer to the SwitchView™ firmware upgrade guide for detailed instructions on updating the switch.

===
Enhancements
===
This release contains the following enhancements incorporated in the indicated versions:

Version 8.12, 05/15/2009
    1. Add hotkey commands: left **Ctrl** and right **Ctrl**

Version 8.11, 03/03/2009
    1. Revise the compatibility of HID Driver.

Version 8.9, 11/26/2008
    1. HOD driver update (for Logitech G15 and Microsoft 8000).
    2. Fix keyboard bug, e.g. missing release key if **Shift**, **Ctrl**, or **Alt** is pressed.

===
Fixes
===

===
Known Issues
===
This release contains no known issues.

```
================================================================
                      Model Applicability
================================================================
```

This release is applicable and available for all SwitchView DVI switch models, which includes the following part numbers:

- 2SVDVI10-xxx
- 4SVDVI10-xxx

NOTE: In the list above, "xxx" is the specific country code for keyboard and power cord localization.