HMX MGR
Revision 2.0.0
Release Notes
May 26[th] 2008

This document outlines:

1. HMXMGR System Firmware Version and Compatibility
2. Important Installation Notes
3. How to Update Firmware
4. Enhancements
5. Fixes
6. Notes

===
HMX MGR System Version and Compatibility
HMX MGR Version 2.0.0 Build# 5430
===
Version 2.0.0 of HMX MGR is intended to be used in a system with the following system component revisions:

- HMIQDI Revision   3.0.0.16
- HMX 1050 Revision   3.0.0.16
- HMIQDHDD Revision   3.0.0.16
- HMX 2050 Revision   3.0.0.16

The following versions of the system components are upgradeable using the HMX MGR version 2.0.0:

- HMIQDI Revisions   2.1.0.13, 2.0.0.9
- HMX 1050 Revisions   2.1.0.13, 2.0.0.9

The following revisions can be upgraded to version 2.0.0.5430:
- 1.0.1.5070
- 1.0.2.5110
- 1.0.3.5251
- 1.0.4.5260

===
Important Installation Notes
===
When the receivers and transmitters are to be upgraded by the HMX MGR, it is recommended that the HMX MGR is upgraded prior to upgrading the receivers and transmitters.

===
How to Update Firmware
===
1. Browse to the IP address of the HMX MGR from a compatible computer.
2. Go to the HMX MGR System tab, select the HMX Manager Server sub-menu and then select the Management Appliance Upgrade facility.
3. You are prompted to browse to the location of the upgrade image.
4. Following the upgrade instructions as provided by the upgrade wizard.

===
Enhancements
===
1. This release adds support for "matrix mode" on the HMX 2050/HMIQDHDD, i.e. the ability to connect to and switch between target computers directly from the HMX 2050 Receiver.
2. Switching times have decreased to approximately 6 seconds.
3. Introduce the ability to reboot the HMX MGR from the browser interface.
4. Introduce the ability to manage firmware files for all HMX system components.

==
Fixes
==
1. On the previous version, it was possible for a user to be denied access to a computer even though that computer was available.

==
Notes
==
1. Before backing up or restoring the database, it is recommended that there be no active sessions present. After restoring the database, it is recommended that you delete all units and add all units again.