VERTIV™

Avocent® AutoView™ Switch for Dell
Firmware Release Notes

VERSION 1.26.4, AUGUST 28, 2017

Release Notes Section Outline

1 Appliance Support Information

2 Enhancements

3 Fixes

4 Notes

5 Client/Browser Information

1 Appliance Support Information

The following appliances are supported with this release.

SWITCH	FIRMWARE
DAV2108	FL0652-AVODELL-1.26.4.0.4286.fl
DAV2216	FL0652-AVODELL-1.26.4.0.4286.fl

2 Enhancements

- DES and 3DES ciphers removed from user interface (keyboard, mouse, video and virtual media)
- Vertiv™ user interface branding
- Improved product security

3 Fixes

L3 #487234-674084682 - VT100 serial IQ module defaulting to the wrong screen mode/width. The IQ module should default to 80 columns and preserve the screen setting during a reboot.

4 Notes

Firmware version 1.26.4 (or higher) is required to support the JAVA 8-based Avocent® DSView™ management software (version 4.5. SP7 or higher) and the Avocent® AutoView™ switch for Dell plug-in (version 1.26.1).

5 Client/Browser Information

NOTE: Microsoft® Internet Explorer® versions 8 and 9 are no longer supported as client browsers.

The following chart indicates the latest version tested.

SOFTWARE	VERSION
Java	Version 8 Update 131
Internet Explorer	11
Firefox	53.0
Firefox ESR	52.0 - 32 bit ONLY
Chrome	58

NOTE: Firefox 52 ESR 64-bit (and higher) is not supported due to the Firefox limits of NPAPI support.