AMIQDM-PS2, AMIQDM-USB, AMIQDM-VSN modules
Firmware Version 4.2.0.7
Release Notes
June 29, 2006

==

This document outlines:

1. AMIQDM module Firmware Version
2. AMIQDM module Firmware Compatibility
3. How to upgrade
4. Fixes

==
AMIQDM module Firmware Version
==

Version Information:

Application Code	4.2.0.7
Boot Code	4.2.0.1
FPGA	2.1.1.0

==
AMIQDM module Firmware Compatibility
==

This revision is compatible with the following firmware:

LV1000R extender	- Full feature support requires 4.3.0.3 or higher.
ECMS1000R extender	- Full feature support requires 4.3.0.3 or higher.

==
How to Upgrade
==

1. Unzip the AMIQ.zip file.
2. Compare the individual boot and application files in the unzipped directory with the versions on the AMIQDM transmitter modules. These versions can be checked on the LV1000R or ECMS1000R extender target OSD.
3. Select which files need to be updated.
4. Follow the upgrade procedure in the product manual to update the unit.
5. Note that if the boot firmware for the unit is updated, then the application and FPGA firmware must also be updated.

==
Fixes
==

This release of firmware contains the following fixes for the AMIQDM modules (since 4.2.0.1) :
   1. In certain circumstances, an AMIQDM module may lose its user assigned name when the AMIQDM module is power cycled.