VERTIV™

Avocent® ACS8xxx Advanced Console System Plug-in for the Avocent® DSView™ Management Software

Release Notes

VERSION 2.4.0.1, AUGUST 24, 2018

Release Notes Section Outline

1   Update Instructions

2   Appliance Firmware Version Information

3   Features and Enhancements

4   TCP Port Information for Communication with the ACS System

1   Update Instructions

IMPORTANT NOTE: The Avocent® ACS8xxx advanced console system plug-in version 2.4.0.1 requires Avocent® DSView™ management software version 4.5 SP8 or higher. It is also recommended to upgrade the ACS8xxx advanced console system firmware to version 2.4.2.

2   Appliance Firmware Version Information

PRODUCT	SOFTWARE TYPE	VERSION	FILENAME
ACS8xxx advanced console system	ACS8xxx advanced console system plug-in for DSView™ software	2.4.0.1	plugin_ACS8000_2.4.0.1_180809.jar.zip plugin_ACS8000_2.4.0.1_180809.jar.zip.md5.txt

3   Features and Enhancements

The Avocent® ACS8xxx advanced console system version 2.4.0.1 plug-in allows you to manage the ACS8xxx advanced console system appliance family from the Avocent® DSView™ software. Please refer to the user guide accompanying the Avocent® ACS8xxx advanced console system for additional details about supported system features.

This release adds support in the Avocent® DSView™ software for the HTML5 serial viewer.

4 TCP Port Information for Communication with the ACS System

The following appliance ports can accept connections from the DSView™ software:

- TCP port 3502 (https)

- TCP port 3871 (adsap2)

- UDP port 3211 (aidp)

- TCP port 22 (sshd)

Additionally, these are the ports in the Avocent® DSView™ software that can accept connections from the appliance:

- TCP port 4122 (default, it can be changed – SSH Server)

- TCP port 4514 (default, it can be changed – Data Logging or Syslog Server)