
Avocent® AutoView™ Switch for Dell

Firmware Release Notes

Version 1.18.2

November 20, 2015

This document outlines:

1. Appliance Support Information
2. Enhancements
3. Fixes
4. Client/Browser Information

1. Appliance Support Information

The following appliances are supported with this release.

Switch	Firmware
DAV2108	FL0652-AVODELL-1.18.2.0.3937.fl
DAV2216	

NOTE: For CentOS targets, you should use a single mouse cursor or a dual mouse cursor with AMS disabled.

2. Enhancements

- OpenSSL updated for “GHOST” vulnerability
- Support for JAVA 8 Update 60
- Support for IBM JAVA
- Support for IE 11 browser
- Improved product security

3. Fixes

- Unable to boot from virtual media ISO image
- Mouse Interface Error during boot of the Dell C6220 server

4. Client/Browser Information

The following chart indicates the latest version tested.

Software	Version
Java	Version 8 Update 60
Internet Explorer	11
Firefox	41
Chrome	46

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and AutoView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.