

VERTIV™

Avocent® AutoView™ Switch for Dell Plug-in for Avocent® DSView™ Management Software Release Notes

VERSION 1.26.1, AUGUST 28, 2017

Release Notes Section Outline

- 1 Enhancements
- 2 Fixes
- 3 Notes

1 Enhancements

- DES and 3DES ciphers removed from user interfaces (keyboard, mouse, video and virtual media)
- Added a Name field to the available fields under appliance IQ adaptors (modules)

2 Fixes

- Avocent® DSView™ management software displays the HDMI USB Speed as N/A, while the On-board Web Interface (OBWI) displays the speed correctly.
- Pushing an IQ adaptor/module/RIP target name greater than 15 characters results in a failed operation with no user feedback. The updated plug-in will successfully push up to 15 characters; names longer than that will be truncated.

3 Notes

- This plug-in requires JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5) and higher.
- This plug-in requires Avocent® AutoView™ switch for Dell firmware version 1.26.4.