

Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance

VMware Deployment Release Notes

VERSION 3.66.8, MAY 2024

Release Notes Section Outline

1. Overview
2. Getting Started
3. Appliance Firmware Version Information
4. Known Issues and Limitations

1. Overview

NOTE: At this time, the former Vertiv™ Avocent® ADX platform is transitioning into the Vertiv™ Avocent® DSView™ solution. During this transition, there may temporarily still be references to “ADX” within product-related features and documentation.

The Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance provides the same features available in the Vertiv™ Avocent® MP1000 Management Platform, just in a virtual environment. However, prior to using the virtual appliance software, license activation is required. See the Vertiv™ Avocent® MP1000 Management Platform User Guide for more information on license activation.

2. Getting Started

The Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance supports VMware vSphere Hypervisor (ESXi 7.0 and 8.0) and VMware vCenter Server (7.0 and 8.0). Vertiv distributes the virtual appliance as an Open Virtual Appliance (OVA) file that includes all necessary components in a single convenient package designed for loading into the VMware vSphere and the VMware vSphere Hypervisor (ESXi). Detailed instructions on deployment and initial set up for the virtual appliance are available in the Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance Installation/Deployment Guide on the [Vertiv™ Avocent® MP1000 Management Platform Virtual Appliance](#) product page under the *Documents & Downloads* tab.

NOTE: If you need additional support, please contact your Vertiv Technical Support representative.

3. Appliance Firmware Version Information

The information in the following table is applicable to this version (V3.66.8). If you are using a different version of the OVA file, the applicable version number will appear in the filename in the following format: AvocentADVirtualAppliance<VERSION>.ova.

NOTE: The latest OVA file version is available on the software download page ([Vertiv™ Avocent® Management Platform Software Download](#)).

APPLIANCE/PRODUCT	VERSION	FILENAME
Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance	3.66.8	AvocentADVirtualAppliance3.66.8.ova

4. Known Issues and Limitations

When deploying the Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance on a VMware vSphere ESXi standalone server, an error occurs to indicate that a required disk image is missing. To resolve this issue, please see section 3.4.2 of the Vertiv™ Avocent® MP1000VA Management Platform Virtual Appliance Installation/Deployment Guide on the [Vertiv™ Avocent® MP1000 Management Platform Virtual Appliance](#) product page under the *Documents & Downloads* tab.