

# Vertiv™ Avocent® AutoView™ 2108/2216 Switch

## Firmware Release Notes

VERSION 2.12.0, JULY 2025

### Release Notes Section Outline

1. Appliance Support Information
2. Enhancements
3. Fixes
4. Notes
5. Client/Browser Information
6. Java Viewer Session Expired Certificate Information

### 1. Appliance Support Information

The following appliances are supported with this release.

| VERTIV™ AVOCENT® AUTOVIEW™ SWITCH | FIRMWARE                    |
|-----------------------------------|-----------------------------|
| AV2108                            | FL0674-AVO-2.12.0.0.1122.fl |
| AV2216                            | FL0674-AVO-2.12.0.0.1122.fl |

**NOTE:** Firmware updates to version 2.8.5 and higher are NOT reversible to firmware versions earlier than 2.8.5.

**NOTE:** Firmware updates between version 1.30.1 and version 2.8.3 are NOT reversible to firmware versions earlier than 1.30.1.

### 2. Enhancements

This release updates the HTML5 viewer.

### 3. Fixes

This release fixes a security issue for authentication bypass.

### 4. Notes

If you wish to enroll the appliance in the Vertiv™ Avocent® DSView™ management software, this firmware version requires the Vertiv™ Avocent® AutoView™ switch plug-in version 1.31.0.

## 5. Client/Browser Information

**NOTE:** Microsoft Internet Explorer is no longer supported as a client browser.

The following chart indicates the latest version tested.

| SFTWARE | VERSION                |
|---------|------------------------|
| Java    | 1.8.0_411-b09          |
| Firefox | 115.12.0esr (64-bit)   |
| Chrome  | 126.0.6478.62 (64-bit) |
| Edge    | 126.0.2592.56 (64-bit) |

## 6. Java Viewer Session Expired Certificate Information

Java KVM viewer session certificates existing in older firmware versions expired on March 6, 2024.. After that date, Java prevents KVM sessions from launching unless you update to the newest firmware or edit the Java Console Security settings on each client computer by adding the appliance IP address in the Exception Site List.