

Vertiv™ Avocent® ACS8xxx Advanced Console System Plug-in for the DSView™ Management Software

Release Notes

VERSION 2.6.0.35, OCTOBER 23, 2020

Release Notes Section Outline

1. Update Instructions
2. Appliance Firmware Version Information
3. Features and Enhancements
4. TCP Port Information for Communication with the Avocent® ACS Console System

1. Update Instructions

IMPORTANT NOTE: The Avocent® ACS8xxx advanced console system plug-in version 2.6.0.35 requires Avocent® DSView™ management software version 4.5 SP12 or higher. It is also recommended to upgrade the Avocent® ACS8xxx advanced console system firmware to version 2.6.4 or later.

2. Appliance Firmware Version Information

PRODUCT	SOFTWARE TYPE	VERSION	FILENAME
Avocent® ACS8xxx advanced console system	Avocent® ACS8xxx advanced console system plug-in for DSView™ software	2.6.0.35	plugin_ACS8000_2.6.0.35_191106.jar.zip plugin_ACS8000_2.6.0.35_191106.jar.zip.sha2.txt

3. Features and Enhancements

This release enables secure enrollment of the Avocent® ACS console system using a 2048-bit certificate by default.

4. TCP Port Information for Communication with the Avocent® ACS Console System

The following appliance ports can accept connections from the Avocent® DSView™ software:

- TCP port 3502 (https)
- TCP port 3871 (adsap2)
- UDP port 3211 (aidp)
- TCP port 22 (sshd)

Additionally, these are the ports in the Avocent® DSView™ software that can accept connections from the appliance:

- TCP port 4122 (default, it can be changed – SSH Server)
- TCP port 4514 (default, it can be changed – Data Logging or Syslog Server)