

---

**Avocent® AutoView™ Switch for Dell**  
**Release Notes**  
**Version 1.8.5**  
**August 12, 2014**

---

This document outlines:

1. Appliance Support Information
2. Fixes

---

**1. Appliance Support Information**

---

The following appliances are supported with this update:

Switch	File Version
DAV2108	FL0652-AVO-1.8.5.0.3546.fl
DAV2216	FL0652-AVO-1.8.5.0.3546.fl

---

**2. Fixes**

---

This update provides improved product security.

---

*Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo and AutoView are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2014 Avocent Corporation. All rights reserved.*

---