

Vertiv[™] Avocent[®] AutoView[™] Switch for Dell Plug-in for Avocent[®] DSView[™] Management Software

Release Notes

VERSION 1.31.0, AUGUST 10, 2020

Release Notes Section Outline

- 1. Enhancements
- 2. Notes

1. Enhancements

This release added support to enroll the appliance in the Avocent® DSView[™] 4.5 management software [Service Pack 10 (SP10) or higher] with 2048-bit certificate.

2. Notes

This plug-in requires the following:

- Java 8-based Avocent® DSView™ 4.5 management software, Service Pack 10 (SP10) and higher.
- Avocent[®] AutoView[™] switch for Dell firmware version 2.4.3.

© 2020 Vertiv Group Corp. All rights reserved. Vertiv[™] and the Vertiv logo are trademarks or registered trademarks of Vertiv Group Corp. All other names and logos referred to are trade names, trademarks or registered trademarks of their respective owners. While every precaution has been taken to ensure accuracy and completeness here, Vertiv Group Corp. assumes no responsibility, and disclaims all liability, for damages resulting from use of this information or for any errors or omissions. Specifications, rebates and other promotional offers are subject to change at Vertiv's sole discretion upon notice.