

VERTIV™

HPE Console Switch G2 Appliance Plug-in for Avocent® DSView™ Management Software Release Notes

VERSION 2.0.0, AUGUST 28, 2017

Release Notes Section Outline

- 1 Enhancements
- 2 Fixes
- 3 Notes

1 Enhancements

- DES and 3DES ciphers removed from user interfaces (keyboard, mouse, video and virtual media)
- Added a Name field to the available fields under appliance IA adaptors (modules)

2 Fixes

Avocent® DSView™ management software displays the HDMI USB Speed as N/A, while the On-board Web Interface (OBWI) displays the speed correctly.

3 Notes

- This plug-in requires JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5) and higher.
- This plug-in requires HPE Console Switch G2 firmware version 2.0.1.