
Avocent® MergePoint Unity™ KVM Over IP and Serial Console Switch Plug-In for DSView™ Management Software

Release Notes

Version 1.26.2

October 6, 2015

This document outlines:

1. Enhancements
2. Fixes

1. Enhancements

- Added support for the Liebert® MPH2 PDU

2. Fixes

- L3 487234-289577258: Alarm threshold parameter configurable
- L3 487234-406638139: MPUIQ-SRL module on cascaded MergePoint Unity™ KVM over IP and serial console switch does not show cascade port connection
- L3 487234-413664113: DSView™ software auto topology update fails with cascade switch / Dell® Blade Chassis
- L3 487234-466880464: Fails to upgrade the switch from DSView™ 4 software session - NMM 104 error

Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo, DSView and MergePoint Unity are trademarks or service marks of Avocent Corporation. Liebert is a trademark or service mark of Liebert Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2015 Avocent Corporation. All rights reserved.