

---

**Avocent® MergePoint Unity™ KVM Over IP and Serial Console Switch  
Plug-In for Avocent® DSView™ Management Software  
Release Notes  
Version 1.32.0  
May 19, 2016**

---

This document outlines:

- 1. Enhancements
- 2. Fixes

---

**1. Enhancements**

---

- Required to support JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5) and higher

**NOTE:** Not compatible with JAVA 7-based DSView™ software from version 4.5.0.108 to 4.5.0.247.

- Removed RC4 encryption settings from user interface

---

**2. Fixes**

---

- L3 #487234-497978818: Enabling FIPS via the Avocent® MergePoint Unity™ switch plug-in results in an unresponsive appliance
- L3 #487234-495262664: Plug-in upgrade issue

*Emerson, Emerson Network Power and the Emerson Network Power logo are trademarks or service marks of Emerson Electric Co. Avocent, the Avocent logo, DSView and MergePoint Unity are trademarks or service marks of Avocent Corporation. All other marks are the intellectual property of their respective owners. This document may contain confidential and/or proprietary information of Avocent Corporation, and its receipt or possession does not convey any right to reproduce, disclose its contents, or to manufacture or sell anything that it may describe. Reproduction, disclosure, or use without specific authorization from Avocent Corporation is strictly prohibited. ©2016 Avocent Corporation. All rights reserved.*