
**Avocent® AutoView™ Switch Plug-in
for Avocent® DSView™ 4.5 Management Software
Release Notes
Version 1.26.0
May 12, 2017**

This document outlines:

1. Enhancements
2. Fixes
3. Notes

1. Enhancements

- DES and 3DES ciphers removed from user interfaces (keyboard, mouse, video and virtual media)
- Added a Name field to the available fields under appliance IQ adaptors (modules)

2. Fixes

- Avocent® DSView™ management software displays MP VMCHD USB Speed as N/A, while the On-board Web Interface (OBWI) displays the speed correctly.
- Pushing an IQ adaptor/module/RIP target name greater than 15 characters results in a failed operation with no user feedback. The updated plug-in will successfully push up to 15 characters and names longer than 15 characters will be truncated.

3. Notes

- This plug-in requires JAVA 8-based Avocent® DSView™ management software, version 4.5. SP5 (Service Pack 5) and higher.
- This plug-in requires Avocent® AutoView™ switch firmware, version 1.26.

© 2017 Vertiv Co. All rights reserved. Vertiv and the Vertiv logo are trademarks or registered trademarks of Vertiv Co. All other names and logos referred to are trade names, trademarks or registered trademarks of their respective owners. While every precaution has been taken to ensure accuracy and completeness herein, Vertiv Co. assumes no responsibility, and disclaims all liability, for damages resulting from use of this information or for any errors or omissions. Specifications are subject to change without notice.